MOTHER-32™ | 2-TIER VERTICAL RACK KIT

① WHAT'S INCLUDED

**ⓐ RACK SIDES**

x2

ⓑ CROSSBAR

x1

ⓒ PAN HEAD SCREWS

x8

② WHAT'S NEEDED

ⓐ PHILLIPS HEAD SCREWDRIVER

x1

ⓓ WASHERS

x8

ⓔ RUBBER FEET

x2

ⓕ RACK INSTRUCTION SHEET

x1

ⓑ MOTHER-32 (OR EMPTY CASE)

x2

③ RACK ASSEMBLY INSTRUCTIONS

ⓐ Remove the top 2 screws from each wood side of your Mother-32.
Note: The lower 2 screws on each wood side should not be removed.

**ⓑ** With each unit positioned on its side, place one rack side-piece in position and loosely reinstall the side screws with the included washers.

ⓒ Repeat step (b) for the opposite side.

ⓓ Install the rubber feet to the bottom of the crossbar with the included screws.

ⓔ Loosely install the crossbar between the rack side-pieces with the included screws.

ⓕ Tighten all screws to stabilize the system.

moog®

MOTHER-32™ | 3-TIER VERTICAL RACK KIT

## ① WHAT'S INCLUDED

ⓐ RACK SIDES

x2

ⓑ CROSSBAR

x1

ⓒ PAN HEAD SCREWS

x8

② WHAT'S NEEDED

**ⓐ PHILLIPS HEAD SCREWDRIVER**

x1

ⓓ WASHERS

x12

ⓔ RUBBER FEET

x2

ⓕ RACK INSTRUCTION SHEET

x1

ⓑ MOTHER-32 (OR EMPTY CASE)

x3

③ RACK ASSEMBLY INSTRUCTIONS

ⓐ Remove the top 2 screws from each wood side of your Mother-32.
   Note: The lower 2 screws on each wood side should not be removed.

ⓑ With each unit positioned on its side, place one rack side-piece in position and loosely reinstall the side screws with the included washers.

ⓒ Repeat step (b) for the opposite side.

ⓓ Install the rubber feet to the bottom of the crossbar. with the included screws.

ⓔ Loosely install the crossbar between the rack side-pieces with the included screws.

ⓕ Tighten all screws to stabilize the system.

moog®